Superfund hazardous waste site listed under the

adjusted Final 1877 NPL-47-2-227 Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) as amended in 1986

> PASCO SANITARY LANDFILL Pasco, Washington

Conditions at listing (June 1988): Pasco Sanitary Landfill covers 250 acres 1.5 miles northeast of Pasco, Franklin County, Washington, in an area dominated by irrigated agricultural fields and range land. The landfill is privately owned and operated and was converted from a burning dump to a sanitary landfill in 1971. Since 1982, it has had a conditional use permit from the Washington Department of Ecology (WDOE) to accept municipal wastes.

In 1972, Resource Recovery Corp. leased a portion of the landfill and operated a regional hazardous waste disposal site under a WDOE permit until December 1974, when the lease terminated.

According to WDOE files, over 47,000 drums of hazardous substances including paint wastes, pesticides, organic solvents, cadmium, and mercury, were deposited in the leased portion of the landfill. In 1974, the area was covered by 3 feet of soil.

In 1985, EPA detected tetrachloroethylene and trichloroethylene in onsite ground water. A well on-site supplies drinking water to two nearby residences. Ground water within 3 miles of the site is used by over 1,000 people for drinking and is also used to irrigate almost 10,000 acres of land.

In October 1986, WDOE issued an Administrative Order requiring Resource Recovery Corp. to monitor on-site wells on a quarterly basis. The company is currently complying with the order.

Status (December 1989): Resource Recovery Corp. has completed a hydrogeological evaluation of the site and continues to monitor on-site wells on a quarterly basis.



Pasco Sanitary Landfill Facility name: . Pasco, Washington Location: 10 EPA Region: Person(s) in charge of the facility: Larry Dietrich Lynn Guilford Date: _ General description of the facility: (For example: landfill, surface impoundment, pile, container; types of hazardous substances; location of the facility; contamination route of major concern; types of information needed for rating; agency action, etc.) Resource Recovery Corporation operated a portion of Pasco Sanitary Landfill as a hazardous waste disposal site from 1972 to 1974. Currently the disposal areas are all covered with three feet of soil. This cover gives both the surface water and direct contact routes scores of O. The ground water route has an observed release and a large ground water population giving the site an overall score of 44.46 Scores: $S_M = 44.46 (S_{qW} = 76.92 S_{SW} = 0 S_a = 0)$ SFE = 0 $s_{DC} = 0$

> FIGURE 1 HRS COVER SHEET

Response to Comments 7.

Ground Water Route Work Sheet							
Rating Factor	Assigned Value (Circle One)	Multi- plier	Coore	Max. Score	Ref. Section)		
1 Observed Release	0 45	1	45	45	3.1		
If observed release is give	n a score of 45, proceed to n a score of 0, proceed to li	ine 4. ne 2.					
2 Route Characteristics	0 1 2 3	2		6	3.2		
Depth to Aquifer of Concern Net Precipitation	0 1 2 3	. 1		3			
Permeability of the Unsaturated Zone Physical State	0 1 2 3	1		3			
	Total Route Characteristics	Score		15			
3 Containment	0 1 2 3	1		3	3.3		
Waste Characteristics Toxicity/Persistence Hazardous Waste Quantity	. 0 3 6 9 <u>12</u> 15 0 1 2 3 4 5	18 1 6 7 (8) 1	12	18 8	3.4		
	Total Waste Characteristic	s Score	20	26			
5 Targets Ground Water Use Distance to Nearest Well/Population Served	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	3 1	9 40	9 40	3.5		
	Total Targets Scor	е	49	49			
6 If line 1 is 45, multip	ly 1 x 4 x 5 2 x 3 x 4 x 5		44100	57.330			
7 Divide line 6 by 57,3	30 and multiply by 100	Sgw	- 76	.92			

FIGURE 2 GROUND WATER ROUTE WORK SHEET John Broke

Surface Water Route Work Sheet							
Rating Factor	Assigned Value (Circle One)	Multi- plier	Coore	Max. Score (S	ection)		
1 Observed Release	0 45	1		45	4.1		
If observed release is give	on a value of 45, proceed to line	4.					
If observed release is give	n a value of 0, proceed to line	<u>. </u>			4.2		
Route Characteristics Facility Slope and Interv	ening (0) 1 2 3	1.		3			
Terrain	① 1 2 3	1 2		3 6			
Distance to Nearest Sur Water Physical State	① 1 2 3	1		3			
,	Total Route Characteristics Sc	ore	0	15			
3 Containment	1 2 3	1	0	3	4.3		
Waste Characteristics Toxicity/Persistence Hazardous Waste Quantity	① 3 6 9 12 15 18 ① 1 2 3 4 5 6	7 8 1	0	18	4.4		
	Total Waste Characteristics S	Score	0	26			
5 Targets Surface Water Use Distance to a Sensitive Environment Population Served/Disto Water Intake Downstream		3 2	0 0 0	9 6 40	4.5		
	Total Targets Score		0	55			
6 If line 1 is 45, multiply 1 x 4 x 5 64.35							
	350 and multiply by 100	Ssw	. 0				

FIGURE 7
SURFACE WATER ROUTE WORK SHEET

Jacoba Pala

	Air Route Work Sheet				
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Max. Score	Ref. Section)
1 Observed Release	0 45	1	0	45	5.1
Date and Location:					
Sampling Protocol:					
If line 1 is 0, the S _a =	0. Enter on line 5.				
Waste Characteristics Reactivity and	0 1 2 3	1		3	5.2
Incompatibility Toxicity Hazardous Waste Quantity	0 1 2 3 0 1 2 3 4 5 6	7 8 1		9 8 	
	Total Waste Characteristics S	Score		20	
3 Targets Population Within 4-Mile Radius Distance to Sensitive) 0 9 12 15 18 } 21 24 27 30 0 1 2 3	1 2		30 6	5.3
Environment Land Use	0 1 2 3	1		3	
	Total Targets Score			39	
4 Multiply 1 x 2 x	3			35,100	
5 Divide line 4 by 35.	100 and multiply by 100	Sa	-	0	

FIGURE 9 AIR ROUTE WORK SHEET

	S	s²
Groundwater Route Score (Sgw)	76.92	5916.69
Surface Water Route Score (S _{SW})	0	0
Air Route Score (Sa)	0	0
$s_{gw}^2 + s_{sw}^2 + s_a^2$		5,916.69
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2}$		76.92
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2} / 1.73 = s_M =$		44.46

FIGURE 10 WORKSHEET FOR COMPUTING $\mathbf{S}_{\mathbf{M}}$

March Tool

		Fire a	nd (Exp	losi	on	Wo	rk	She	et				
	Rating Factor	As	ssig (Cir	nec	Va One	lue e)					Multi- plier	Score	Max. Score	Ref. (Section)
1	Containment	1				;	3				1		3	7.1
2	Waste Characteristics Direct Evidence Ignitability Reactivity Incompatibility Hazardous Waste Quantity	-	1 1 1 1	2 2 2 2	3 3 3 3	4	5	6	7	8	1 1 1 1		3 3 3 3 8	7.2
		Total Was	ste	Cha	ırac	teri	stic	s	Scor	е	,		20	
3	Targets Distance to Nearest	0	1	2	3	4	5				1		5	7.3
	Population Distance to Nearest	0	1	2	3						1		3	
	Building Distance to Sensitive	0	1	2	3						1		3	
	Environment Land Use	0	1	2	3						1		3	
	Population Within	0	1	2	3	4	5				1		5	
	2-Mile Radius Buildings Within 2-Mile Radius	0	1	2	3	4	5				1		5	
		т	ota	ı Ta	rae	ts 5	Sco	re				1	24	7
			ota	- I d	- Ge			. 0				-		+
4	Multiply 1 x 2 x	3											1,440	
5 Divide line 4 by 1,440 and multiply by 100 SFE = 0														

FIGURE 11
FIRE AND EXPLOSION WORK SHEET

	Direct Contact Work Sheet Assigned Value	Multi- plier	Score	Max. Score	Ref. (Section)
Rating Factor	(Circle One)			45	8.1
1 Observed Incident	0 45	1		4.5	
If line 1 is 45, proceed	to line 4			1	
2 Accessibility	0 ① 2 3	1	1	3	8.2
3 Containment	① 15	1	0	15	8.3
Maste Characteristics	0 1 2 3	5	0	15	8.4
Toxicity	0,10			20	8.5
Targets Population Within a	<pre>0 1 2 3 4 5</pre>	4	0	20	
1-Mile Radius Distance to a	0 1 2 3	4	0	12	ε,
Critical Habitat					
			*,		
_			T.	0 3	2
	Total Targets Score				
6 If line 1 is 45, mul	tiply 1 × 4 × 5 ply 2 × 3 × 4 × 5			0 21.	600
7 Divide line 6 by 2		St	oc -	0	

FIGURE 12 DIRECT CONTACT WORK SHEET Hadla Dale



ecology and environment, inc.

101 YESLER WAY, SEATTLE, WASHINGTON, 98104, TEL. 206/624-9537

International Specialists in the Environment

DOCUMENTATION RECORDS

FOR

HAZARD RANKING SYSTEM

Instructions: The purpose of these records is to provide a convenient way to prepare an auditable record of the data and documentation used to apply the Hazard Ranking System to a given facility/site. As briefly as possible summarize the information you used to assign the score for each factor (e.g., "Waste Quantity = 4320 drums plus 800 cubic yards of sludges"). The source of the information should be provided for each entry and should be a biographical-type reference that will make the source used for the data point easier to find. Include the location of the source and consider appending a copy of the relevant page(s) for ease in review.

FACILITY NAME: Pasco Sanitary Landfill

LOCATION: Kahlotus Road and Highway 12

Pasco, Washington 99301

REVIEWER: Lynn Guilford

TDD: TDD F10-8701-04

ECOLOGY AND ENVIRONMENT, INC.

DATE: June 1987

Machini By

GROUND WATER ROUTE

- OBSERVED RELEASE
- 1a. Contaminants Detected (5 maximum) in Ground Water

Tetrachloroethylene was found in monitoring well EE2.

Trichloroethylene was found in monitoring wells EE2, EE3, and JUB 2.

The levels found were significantly over background (JUB-CNTR)

- Rationale for attributing the contaminants to the facility:

These compounds, tetrachloroethylene and trichloroethylene, were not found in background wells, but were only found in wells downgradient and adjacent to zone A and the old landfill burn and demolition disposal area. Paint wastes were disposed in Zone A.

HRS Section Score: 45 (Ref. 1 p.s.e)

* * * * * * * * *

- ROUTE CHARACTERISTICS
- 2a. Depth to Aquifer of Concern
 - Name and description of aquifer(s) of concern:

 Water table aquifer, unconfined, which overlies

 Vakima Basalts, Groundwater occurs 33.5 to 68.7 feet

 below ground surface at site, see table 4.1 and figures

 below ground surface at site, see table 4.1 and figures

 HIL and HIB of Reference I for description of geologic

 units and cross-sections.

HRS Section Score: (Ref.

2b. Net Precipitation

- Mean annual or seasonal precipitation (list months for seasonal):
- Mean annual lake evaporation rate (list months for seasonal):
- Net precipitation (subtract above figures):

HRS Section Score: (Ref.

March 17.17.8

20	Permeability	of	Unsaturated	Zone
	1 61 111000	-		

- Soil type in unsaturated zone:
- Permeability associated with soil type:

HRS Section Score: (Ref.

2d. Physical State

- Physical state of substance at time of disposal (or at present time for generated gases):

HRS Section Score: (Ref.

* * * * * * * * *

- 3. CONTAINMENT
- 3a. Containment
 - Method(s) of waste or leachate containment evaluated:
 - Method with highest score:

HRS Section Score: (Ref.

* * * * * * * * *

- 4. WASTE CHARACTERISTICS
- 4.a Toxicity and Persistence
 - Compound(s) evaluated:

Compound	Toxicity	Persistence	Total	-
Trichloroethylene Tetrachloroethylene	2 2	2 2	12 12	

- Compound(s) with highest score:

Tetrachloroethylene and Trichloroethylene

HRS Section Score: 12 (Ref. 2

4b. Hazardous Waste Quantity

- Total amount of hazardous substance at the facility, excluding those with a containment score of zero. (Give a reasonable estimate, even if the quantity is above maximum.):

The total waste quantity is estimated to be approximately 47,000 drums.

Basis of estimating and/or computing waste quantity (must be documented quantity and not assumed):

Paint Wastes - 26,426 drums 2,4-D Mfg. wastes - 5,080 drums Carcinogenics - 9 drums Aromatic Tar -1,159 drums Cadmium Waste - 11 drums Pesticides - 425 drums
Metal Finishing/Cleaning
- 10,947 drums
Solvents - 253 drums
Barium with Mercury
- 2,896 drums

HRS Section Score: 8 (Ref. 1,3,4,5)

* * * * * * * *

TARGETS

5a. Ground Water Use

- Use(s) of aquifer(s) of concern within a 3-mile radius of the facility:

Ground water is used for drinking water and irrigation within three miles of the site. Some of the wells used for drinking water are beyond the perimeter of the public water supply system.

HRS Section Score: 3 (Ref. 6,7,8, 9,10,11,12,13)

5b. Distance to Nearest Well

Location of nearest well drawing from the "aquifer of concern" or occupied building not served by a public water supply:

SW 1/4, NW 1/4, Section 22, Township 9N, Range 30E.

- Distance from site to above well or building:

The well is on site, approximately 800 feet north of monitoring wells EE2, EE3, and JUB 2, which are contaminated.

HRS Section Score: 4 (Ref. 11,13

5c. Population Served by Ground Water within a 3-Mile Radius

 Identify water supply well(s) drawing from the "aquifer of concern" within a 3-mile radius and populations served by each:

See sheet 4A.
Total 260

 Compute land area irrigated by supply well(s) drawing from the "aquifer of concern" and convert to population (1.5 people per acre):

See Sheets 4B,C,D Total 14,820 people

- Total population served by ground water:

260+14820=15080

HRS Section Score: 40 (Ref. 7,8,9, 10,11,12,13,14)

Res. Comm.

Harden 17-87

Pasco Sanitary Landfill

6 | 5 | 87

*	• .		
GW used for dru	iting water	within 3 mi	les of above site
Name	Pop server	Reference	**
Washington Idaho Laborers	8, E	7	
. Paul Bauage	3.8	7	
. Al Yenney	3,8	7	
Tom Kidwell	3.8		
Ven Wormer	3.8	7	
. Lakeview Mobile Home Park	83.6	19 19	
7. Rada Sons	15.0		
		19	
q. AZTLAN Construction Inc	5	11	7.
10. BPA - Franklin	16	19	
11. Bonne Brae Trailer Court	57		
12. De Vries Water system	15	8	
13. Palmarez	3. g	10	
14. Marquez	3,8	10	
15. Johnson & Boxbaum	3 ' 2	10	
16. Bumgarner	3.8	10	
17. Dall	3,8	10	
18. Conningham	3,8	/0	
19. Rasmussen	3.8	10	o Comm.
20. Western Farm Services	4	19 1 <i>9</i>	Res. Comm.
21, Frontier Machinery	22	17	1-4-90 1-4-90
Toto	al 260		- 1.6
			2 Depto

March 17-87

6/10/87

•		1 .
Pasco Sa	nitary Landfill	6/10/87
Ew wed for irrigation	within 3 miles	of above site;
Name		ncterence #
Burlington Northern	290	q
$\supset_{\mathfrak{n}}$	130	
Conn Mut Life Ihs	145	
Conn Mut Life Ihs Burlington Northern	290	
211	290	
11	300	
Middleton	142	
11	20	
Columbia East	268	****
Burlington Northern	13 7	² 2,
Doi magran	160	
W.	400	
11	315	
,	107	
11	300	
11	200	
Sullivak	.70	
	107	
Burlington Northern	300	1
10	40	1
Alderson	150	
columbia East	200	1.1
Colombia East	315	dol
Burlington Northern	40	a alto De
11	75	Letter 187
#11/	15	Madro 187
	10	17
USCE	Ų	

Standard OII Minnchan Conn Mut Life Ins Tippett IGO Conn Mut Life Ins. IGO Worsham Cox II Conn Mut Life Ins II So Worsham Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardwave Clase Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner Reisinger		·
Conn Mut Life Ins Tippett Tippett Conn Mut Life Ins. Conn Mut Life Ins. Cox Is7 Conn Mut Life Ins. Is7 Is7 Is7 Is7 Is7 Is7 Is7 I	Standard Oil	.75
Conn Mut Life Ins 137 Tippett 135 Conn Mut Life Ins. 160 Worsham 157 Cohn Mut Life Ins 130 Worsham 157 Worsham 157 Burlington Northern 460 WA ST DNR 520 Columbia East 130 Burlington Northern 130 Seattle Hardwave 14 Clase Modd 2 Fanning Frontier Machinery 12:5 Pasco, City ot 15 Columbia Dietrich 38 Tomlinson 268 Burden 395 Burden 40 Spooner	Minnahan	40
Conn Mut Life Ins. 160 Worsham Cox 157 Cohn Mut Life Ins 157 Worsham Borlington Northern Columbia East Builington Northern Seattle Hardwave Close Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Conn Mut Life Ins	137
Conn Mut Life Ins. 160 Worsham Cox 157 Conn Mut Life Ins 130 Worsham 157 Worsham 157 Burlington Northern 460 WA ST DNR 520 Columbia East 130 Seattle Hardwave 130 Seattle Hardwave 11 Frontier Machinery 12,5 Frontier Machinery 12,5 Columbia 268 Dietrich 38 Dietrich 38 Dietrich 38 Dietrich 38 Spooner 5	Tippett	132
Worsham Cox 157 Cohn Hut Life Ins 130 Worsham Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardwave Clase Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palom arez Burden Eastern Wa ID Spooner	1,1	160
Worsham Cox 157 Cohn Hut Life Ins 130 Worsham Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardwave Clase Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palom arez Burden Eastern Wa ID Spooner	Conn Mut Life Ins.	160
Conn that Life Ins Worsham Burlington Northern Columbia East Burlington Northern Seattle Hardwave Close Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		157
Cohn Mut Life Ins 130 Worsham Burlington Northern Columbia East Burlington Northern Seattle Hardware Clase Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	,	157
Worsham Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardwave Close Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich tomlinson Palomarez Burden Eastern Wa ID Spooner	H	5
Worsham Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardwave Clase Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Cohn Mut Life Ins	130
Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardware Close Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		155
Burlington Northern WA ST DNR Columbia East Burlington Northern Seattle Hardware Close Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Worsham	157
Columbia East Builington Northern Seattle Hardware Close Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Burlington Northern	480
Columbia East Builington Northern Seattle Hardware Close Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich tomlinson Palomarez Burden Eastern Wa ID Spooner	WA ST DNR	520
Builington Northern Seattle Hardware Close Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		_
Seattle Hardware close Modd Fanning Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Builington Northern	130
Close Modd Fanning Frontier Machinery Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner	Seattle Hardware	4
Modd Fanning Frontier Machinery 12.5 Pasco, City of Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		1
Frontier Machinery Frontier Machinery Pasco, City ot Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		ک
Pasco, City of Columbia Dietrich Tomlinson Palomarez Palomarez Burden Eastern Wa ID Spooner		7
Pasco, City of Columbia Dietrich Tomlinson Palomarez Palomarez Burden Eastern Wa ID Spooner	Frontier Machinery	12.5
Columbia Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		15
Dietrich Tomlinson Palomarez Burden Eastern Wa ID Spooner		268
tomlinson Palomarez Burden Eastern Wa ID Spooner		38
Burden 20 Eastern Wa ID 5 Spooner	_	345
Eastern Wa ID Spooner	Palom arez	26
Eastern Wa ID Spooner	Burden	20
Spooner	- •	5
Reisinger		1
	Reisinger	2

Hardian Fine

Reisinger Mann 515 Johnson Lourdes 15 Pasco, City of Pasco, Port of 10 Columbia East 495 73 Story 4111 20 100 USCE Total 9879.75 acres people per x 1.5 14820

Macha Depolat

SURFACE WATER ROUTE

- OBSERVED RELEASE
- 1a. Contaminants Detected in the Surface Water at the Facility or Down Gradient from It (5 maximum)

No observed release.

- Rationale for attributing contaminants to the facility:

HRS Section Score:

(Ref.

++++*

- 2. ROUTE CHARACTERISTICS
- 2a. Facility Slope and Intervening Terrain
 - Average slope of facility/s a in percent:

 The site is relatively flat (less than 1%).
 - Name description of nearest down-slope surface water:

 The only down slope water within two miles is a man-made dairy pond.
 - Average slope of terrain between facility and above-cited surface water body in percent:

The average slope is less than 1%.

- Is the facility located either totally or partially in surface water? Yes / No (circle one)
- Is the facility completely surrounded by areas of higher elevation? Yes / No (circle one)

HRS Section Score: 0 (Ref. 1,12,13)

2b. 1-Year 24-Hour Rainfall in Inches

Less than 0.75

HRS Section Score: 0 (Ref. 2



				-	C	11-4
0 -	Distance	+0	Magract	Down-slope	Surface	water
ZC.	Distance	LU	Mediese	DOWN STOPE		

The man-made dairy pond is approximately 1,500 feet southwest of the site. No natural water is located within two miles of the site.

HRS Section Score: 0 (Ref. 1,12,13, 15,16)

2d. Physical State of Substance at Time of Disposal

No known waste is available to surface water migration.

HRS Section Score: 0 (Ref. 1

* * * * * * * * * *

CONTAINMENT

3a. Containment

- Method(s) of waste or leachate containment:

All known hazardous wastes have been covered,

- Method with highest score:

All known hazardous wastes are covered with three feet of soil, four mil polyethylene sheeting, and capped with an additional two feet of soil.

HRS Section Score: 0 (Ref. 1

* * * * * *

4. WASTE CHARACTERISTICS

4a. Toxicity and Persistence

- Compound(s) evaluated:

Compound	Toxicity	Persistence	Total

Jack Babl

- Compound(s) with highest score:

No known compounds are available to migration.

HRS Section Score: 0 (Ref. 1

4b. Hazardous Waste Quantity

 Total amount of hazardous substance at the facility/site, excluding those with a containment score of zero. (Give a reasonable estimate, even if the quantity is above maximum.):

No known waste is available to surface water migration.

- Basis of estimating and/or computing waste quantity (must be documented and not assumed):

HRS Section Score: 0 (Ref. 1

* * * * * * * * *

TARGETS

5a. Surface Water Uses

- Use(s) of surface water within 3-miles downstream of the hazardous substance:

No natural surface water is used within two miles of the site and no known hazardous wastes are available to migration.

- Is there tidal influence?

Yes / No (circle one)

HRS Section Score: (Ref. 1

5b. Distance to Sensitive Environment

- Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:
- Distance to 5-acre (minimum) fresh-water wetland, if 1 mile or less:
- Distance to critical habitat of federal endangered species or national wildlife refuge, if 1 mile or less:

HRS Section Score: 0 (Ref.

5c. Population Served by Surface Water

 Location(s) of water-supply intake(s) within 3 miles (free-flowing bodies) or 1 mile (static bodies) downstream of the hazardous substance and population served by each intake:

No known wastes are available to surface water. No natural surface water is located within two miles of the site.

- Compute land area irrigated by above-cited intake(s) and convert to population (1.5 people per acre):
- Total population served: 0
- Name and description of nearest above-cited water bodies:
- Distance from probable point of entry to above-cited intakes (stream miles):

* * * * * * * *

March 20 10 10

AIR ROUTE

1.	OBSERVED RELEASE
1a.	Contaminants Detected in Ambient Air
	None observed.
-	Date and location of detection of contaminants:
-	Method used to detect contaminants:
-	Rationale for attributing contaminants to the site:
	HRS Section Score: 0 (Ref. 1,15)
	* * * * * * * *
2.	WASTE CHARACTERISTICS
2a.	. Reactivity and Incompatibility
	- Most reactive compound:
	- Most incompatible pair of compounds:
	HRS Section Score: (Ref.)
2b	. <u>Toxicity</u>
	- Most toxic compound:
	<u>Compound</u> Toxicity
	HRS Section Score: (Ref.

2c. Hazardous Waste Quantity

- Total quantity of hazardous waste at the facility/site:

Malle Police

- Basis of estimating and/or computing waste quantity:

HRS Section Score:

(Ref.

* * * * * * * *

TARGETS

3a. Population Within 4-mile Radius

- Enter data under respective radius and indicate how determined:

0 to 4 miles	0 to 1 mile	O to 1/2 mile	O to 1/4 mile
1			

HRS Section Score:

(Ref.

3b. Distance to Sensitive Environment

- Distance to 5-acre (minimum) coastal wetlands, if 2 miles or less:
- Distance to 5-acre (minimum) fresh-water wetland, if 1 mile or less:
- Distance to critical habitat of an endangered species, if 1 mile or less:

HRS Section Score:

(Ref.

3c. Land Use

- Distance to commercial/industrial area, if 1 mile or less:
- Distance to national or state park, forest, or wildlife reserve, if 2 miles or less:
- Distance to residential area, if 2 miles or less:
- Distance to agricultural land in production within past 5 years, if 1 mile or less:

land the Daniel

- Distance to prime agricultural land in production within past 5 years, if 2 miles or less:
- Is a historic or landmark site (National Register of Historic Places and National Natural Landmarks) within the view of the site:

HRS Section Score:

(Ref.

Hadra Doll

FIRE AND EXPLOSION

FIRE MARSHAL'S STATEMENT:			
This site poses no fire/explosi	ive potential (Ref. 16).		
1. CONTAINMENT		* * .	
- Hazardous substance present:			
- Type of containment, if applica	able:		
* * * * *	<pre>HRS Section Score:</pre>	(Ref.)
2. WASTE CHARACTERISTICS			
2a. Direct Evidence			
- Type of Instrument and Measure	ment:	te,	
	HRS Section Score:	(Ref.)
2b. <u>Ignitability</u>			
- Compound considered:			
	HRS Section Score:	(Ref.)
2c. Reactivity			
- Most reactive compound:			
	HRS Section Score:	(Ref.)
2d. <u>Incompatibility</u>Most incompatible pair of companies	pounds:		
	HRS Section Score:	(Ref.	8

2e. Hazardous Waste Quantity	*.		
- Total quantity of hazardous sub	stance(s) at the facili	ty/site:	
- Basis for estimating and/or com	puting waste quantity:		*
	HRS Section Score:	(Ref.)
* * * * *	* * * *		
3. TARGETS			
3a. Distance to Nearest Population			
	HRS Section Score:	(Ref.)
3b. Distance to Nearest Building			
	HRS Section Score:	(Ref.	
3c. Distance to Nearest Sensitive E	Environment		
- Distance to wetlands:			
- Distance to critical habitat:			
	HRS Section Score:	(Ref.	

3d. Land Use

- Distance to commercial/industrial area, if 1 mile or less:
- Distance to national or state park, forest, or wildlife refuge, if 2 miles or less:
- Distance to residential area, if 2 miles or less:
- Distance to agricultural land in production within past 5 years, if 1 mile or less:

···	Distance to prime agricultural laif 2 miles or less: Is a historic or landmark site w			
		HRS Section Score:	(Ref.)
3e.	Population Within 2-Mile Radius			
		HRS Section Score:	(Ref.)
3f.	Buildings Within 2-Mile Radius			
		UDS Section Score:	(Ref)

Market Stall

DIRECT CONTACT

- OBSERVED INCIDENT
- la. Date, Location, and Pertinent Details of Incident

No observed incident reported.

HRS Section Score: 0 (Ref. 1,15

* * * * * * * * *

- 2. ACCESSIBILITY
- 2a. Describe Type of Barrier(s)

Site is not fenced. However, the operator's residence is on site.

HRS Section Score: 1 (Ref. 17)

* * * * * * * * *

- CONTAINMENT
- 3a. Type of Containment, if Applicable

The known hazardous waste is covered with three feet of soil, four mil polyethylene sheeting, and capped with an additional two feet of soil.

HRS Section Score: 0 (Ref. 1)

* * * * * * * * * *

- 4. WASTE CHARACTERISTICS
- 4a. Toxicity
 - Compounds evaluated:

Compound Toxicity

No compounds available for contact.

- Compound with highest score:

Control of the second

HRS Section Score: 0 (Ref. 1

* * * * * * * * * *

- 5. TARGETS
- 5a. Population Within 1-mile Radius of Site No compounds available for contact.

HRS Section Score: (Ref. 1

5b. Distance to Critical Habitat (of Endangered Species)

HRS Section Score: (Ref.

* * * * * * * *

Washing Frede

REFERENCES

- Ecology and Environment, Inc., June 1986. Final Report for Resource Recovery Corporation, Pasco, Washington.
- U.S. Environmental Protection Agency (USEPA), 1984, Uncontrolled Hazardous Waste Site Ranking System, A User's Manual. 47FR 31220-31241.
- Kimberly Jr., John R., President, Resource Recovery Corporation, July 2, 1980. Letter to Department of Ecology.
- Washington Department of Ecology, Dec. 1973. <u>Industrial Waste Disposal Site Evaluation</u>.
- Resource Recovery Corporation, June 11, 1973 to January 17, 1975, Monthly Waste Summaries to Washington Department of Ecology.
- 6. Personal Communication, May 27, 1987. Pat Barttels, City of Pasco Engineering Department, Engineering Technician, to Charles F. Pitz, E&E, Seattle.
- Washington State Well Logs.
- State of Washington Public Water Supply System Listing.
- 9. Washington State Water Rights Data.
- 10. U.S. Geological Survey Well Records.
- 11. Washington State Well Log for John Dietrich's Well located at SW 1/4, NW 1/4, Sec. 22, T9N, R30E.
- U.S. Geological Survey (USGS), 1964. Pasco, Washington, Quadrangle Map, 7.5 Minute Series, Photo Revised 1973.
- 13. U.S. Geological Survey (USGS)), 1979. <u>Glade, Washington</u> Quadrangle Map, 7.5 Minute Series.
- Personal Communication, May 28, 1987. Cindy Christian, Washington Department of Ecology, Eastern District Office, to Charles F. Pitz, E&E, Seattle.
- 15. Personal Communication, May 29, 1987. Jean Tomlinson to Gloria Skinner, E&E, Seattle.
- Personal Communication, June 1, 1987. Don Carter, Franklin County Fire Marshall to Gloria Skinner, E&E, Seattle.
- 17. Ecology and Environment, Inc., January 1985. Preliminary Site Inspection Report of Resource Recovery Corporation, Pasco, Washington.
- 18, Personal Communication with Richard Heinemayer
- 19. Telephone Juruey of Drinking Water Usage of Ground Water, 7/19/88

1-4-90 1-4-90

Actual: 8=.60

1.1.1 25 km



PASCO SANITARY LANDFILL

Groundwater Usage Information Sheet
Owner: Lakeview Mubile Home Park Contact Date: 3/19/88
Phone No: 547.3062 Contact Made By: 6 Kuit
Address: S. 1505 Rd. 40 E.
Pasco, Na. 99301
Person Contacted: Signed: (())()()
Is well used for Drinking Water?: Yes $[\cline{igg<}]$ No $[\cline{igg<}]$
No. of permanent people served: 32 Spaces
Is well used for Irrigation?: Yes $[X]$ No $[]$
No. of acres:
Comments: (1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Comments: Micalici La Terring Carin
×
Drinking Water Users
Actual vs. EPA Estimate

Owner: Radia Sins	Contact Date: 7/19/55
Phone No: 547-3974	Contact Made By:
Address: 2707 FIEWIS PASCO, WA	
Person Contacted:	Signed: (Milla Mad
Is well used for Drinking Water?: No. of permanent people served:	Yes [∀] No [] Yes [∀] No []
Is well used for Irrigation?: No. of acres:	
Comments:	
	ring Water Users vs. EPA Estimate

Owner: Azian Const (Don Norvell) Contact Date: 1/19/88
Phone No: 545-1985 Contact Made By:
Address: 2100 E. Lewis
Person Contacted: Don Norvell Signed: Phone
Is well used for Drinking Water?: Yes [/] No [] No. of permanent people served:
Is well used for Irrigation?: Yes [] No []
No. of acres:
Comments:
Drinking Water Users
Actual vs. EPA Estimate
Patriola (%)

	가게 되는 하세요? 그렇게 되었다.
Owner: Bonnie Brae Tr. Crt.	Contact Date: 1/19/58
Phone No: 547-4005	Contact Made By: 6 ACucture
Address: 2508 E. Luces	<u> </u>
Person Contacted: Saw aune	signed: Sunt aure
Is well used for Drinking Water?:	Yes [V] No []
No. of permanent people served:	Yes [1] No [] 50-55-Monthly Rotals-1 Agent. (accomins) Yes [1] No []
Is well used for Irrigation?:	Yes [] No []
No. of acres:	3.97 deres
Comments:	
	i di Natara Managa
Drink	ing Water Users
Actual	vs. EPA Estimate
Actual:57	EPA: 65

Owner: Western Farm Services	Contact Date: 7/19/50
Phone No: 545 - 4900	Contact Made By: South
Address: 15/ Dietrich Rd	• •
Person Contacted: Jean Piting	Signed: Jean Piter,
Is well used for Drinking Water?: Yes [
No. of permanent people served:	4
Is well used for Irrigation?: Yes [] No [4]
No. of acres:	
Comments:	
•	
Drinking Wate	r Users
Actual vs. EPA	Estimate
Actual: 4/ EPA:	24

Actual: 22

PASCO SANITARY LANDFILL

Owner: Frontier Marhinery : Contact Date: 7/19/88
Owner: Frantier Marhinery Contact Date: 7/19/88 Phone No: 1970 (5) 11 Contact Made By: 6 Orithme
Address: 1700 E Jaines
127500 LA 99301
Person Contacted: Donner (RIER Signed: (CIVICE)) (Contacted)
Is well used for Drinking Water?: Yes [] No []
No. of permanent people served: 22
Is well used for Irrigation?: Yes [] No [$igtherapsilon$
No. of acres:
comments: Used To IRRIGATE Field but STOPPED
Comments: Used To IRRIGATE. Field but stopped. Sought years Ago - NOW only domestic use.
K.A.
(1 west rece & Criticis
Drinking Water Users
Actual vs. EPA Estimate